




COMMON COMPONENTS

Z1901-2/3/4-32/33

12X12 [305X305] A.R.E SANI-FLOR RECEPTOR 8 [203] SUMP DEPTH W/ 1/2 GRATE,
3/4 GRATE, FULL GRATE W/ OPENING AND ALUMINUM DOME STRAINER, WHITE A.R.C.
ANTI SPLASH BOTTOM DOME STRAINER

Design and Dimensional Data (inches and [mm]) are Subject to Manufacturing Tolerances and Change Without Notice



* Customer to Specify Size

⚠ **WARNING:** Cancer and Reproductive Harm - www.P65Warnings.ca.gov

⚠ **ADVERTENCIA:** Cáncer y daño reproductivo - www.P65Warnings.ca.gov

⚠ **AVERTISSEMENT:** Cancer et effets néfastes sur la reproduction - www.P65Warnings.ca.gov

Zurn Industries, LLC | Specification Drainage Operation
1801 Pittsburgh Avenue, Erie, PA 16502, Ph. 855.663.9876

In Canada | Zurn Industries Limited
7900 Goreway Drive, Unit 10, Brampton, Ontario L6T 5W6, Ph. 877.892.5216

www.zurn.com

Rev. B
Date: 01/12/23
C.N. No. 144899
Patent zurn.com/patents
Prod. | Dwg. No. FS20

Page 1 of 2




COMMON COMPONENTS

ZS1901-HD-K-SA

12X12 [305X305] A.R.E SANI-FLOR RECEPTOR 8 [203] SUMP DEPTH W/ STAINLESS STEEL FRAME AND EXTRA-HEAVY DUTY STAINLESS GRATE, ANCHOR FLANGE, AND STABILIZER ASSEMBLY

Design and Dimensional Data (inches and [mm]) are Subject to Manufacturing Tolerances and Change Without Notice



* Customer to Specify Size

⚠ **WARNING:** Cancer and Reproductive Harm - www.P65Warnings.ca.gov

⚠ **ADVERTENCIA:** Cáncer y daño reproductivo - www.P65Warnings.ca.gov

⚠ **AVERTISSEMENT:** Cancer et effets néfastes sur la reproduction - www.P65Warnings.ca.gov

Zurn Industries, LLC | Specification Drainage Operation
1801 Pittsburgh Avenue, Erie, PA 16502, Ph. 855.663.9876

In Canada | Zurn Industries Limited
7900 Goreway Drive, Unit 10, Brampton, Ontario L6T 5W6, Ph. 877.892.5216

www.zurn.com

Rev. B
Date: 01/12/23
C.N. No. 144899
Patent zurn.com/patents
Prod. | Dwg. No. FS20

Page 2 of 2